



2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aérodrome de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315

HIGHLIGHTS

13 PASSENGER CONFIGURATION
BATCH 3.3 AVIONICS UPGRADE COMPLIED
FANS 1/A+, ADS-B OUT, TCAS 7.1 COMPLIED
RUNWAY AWARENESS AND ADVISORY SYSTEM
CLASS II ELECTRONIC FLIGHT BAG
FRESH 8C (120 MONTH) INSPECTION AT DUNCAN AVIATION
FORWARD GALLEY, FORWARD CREW LAVATORY, AFT PRIVATE VIP LAVATORY
REFURBISHED WOOD, POLISHED SEATS AND EXTERIOR TOUCH-UPS

AIFRAME

Total Time Since New 3,079 Hours
Total Landings Since New 1,053 Landings
Program Coverage SPP Program

ENGINES

Description	Rolls-Royce BR700-710A2-20	
	Left Engine	Right Engine
Serial Numbers	12813	12814
Total Hours Since New	3,071 Hours	3,071 Hours
Total Cycles Since New	1,050 Cycles	1,050 Cycles
Program Coverage	Rolls-Royce Corporate Care Program	

APU

Description	Honeywell RE220 (GX)
Serial Number	P-439
APU Total Time	3,762 Hours
Program Coverage	MSP Gold Program

2009 Bombardier Global 5000 S/N 9315

AVIONICS

3 Honeywell IC-800 Integrated Avionics Computer
3 Honeywell LASEREF III Inertial Reference Units
3 Honeywell CD-820 FMS Control Display Units
4 Honeywell DA-810 Data Acquisition Units
6 Honeywell DU-870 Display Units
Honeywell Mk V EGPWS
Honeywell Runway Awareness and Advisory System
Honeywell Traffic Collision Avoidance System with change 7.1
2 Honeywell RCZ-833K VHF Integrated Communication Units
1 Honeywell RCZ-833 VHF Communication Unit
2 Rockwell Collins HF-9031A HF Transceivers
2 Honeywell RM-855B Radio Management Unit
Honeywell SSFDR Flight Data Recorder
Honeywell SSCVR Cockpit Voice Recorder
Honeywell GP-400 Flight Guidance Panel
Avtech CSD-714 SELCAL
Honeywell WC-880 Weather Radar
Teledyne TL-608 Airborne Data Link Unit
3 Honeywell AV-850A Audio Panel
2 Telex 903E Microphones
Dukane Underwater Acoustic Beacon
3 Honeywell AZ-940 Micro Air Data Computers
Thales ISI Integrated Standby Instrument
Rockwell Collins SRT-2100-3 SATCOM Receiver/Transmitter
International Communications Group ICS-100 Iridium Transceiver Unit
Artex B406-4 Emergency Locator Transmitter
Honeywell RT-950 TCAS Receiver/Transmitter Unit
2 Rockwell Collins ALT-4000 Radio Altimeter Receiver/Transmitter
Honeywell LP-860 Lightning Sensor Processor
2 Honeywell RNZ-851 VHF Integrated Navigation Units
2 Honeywell Mark II Global Navigation System Sensor Units
Rockwell Collins WLU-2100 Wireless Access Service Point

MAJOR INSPECTION STATUS

Inspection	Last Performed	Next Due
15 Month*	20 September 2019	24 June 2020
30 Month*	20 September 2019	23 December 2021
60 Month*	20 September 2019	25 June 2024
120 Month*	20 September 2019	25 June 2029
Landing Gear Overhaul	Not Applicable	25 June 2029

These inspections were completed at Duncan Aviation Battle Creek

NAVIGATION & COMPLIANCE

ADS-B OUT FANS 1/A+
TCAS 7.1
Batch 3.3 Avionics Upgrade

2009 Bombardier Global 5000 S/N 9315

INTERIOR

The aircraft underwent a cabin refurbishment at Duncan Aviation in 2019. The wood has been refurbished throughout the cabin, the divan was replaced and the leather seats were touched up and polished.

13 Passenger Configuration

- Forward Cabin: Four place club seating arrangement
- Mid Cabin: Four place dining or conference grouping opposite a credenza
- Aft Cabin: Two place club seating arrangement opposite a three-place berthing divan
- Observer Seat: The observer seat stows in the LH crew wardrobe when not in use
- Lavatory: Forward crew lavatory and aft private VIP lavatory

Forward Galley Featuring

- Ample storage for china, crystal, utensils,
- Sealed trash container
- Coffee maker with slide out tray, espresso maker on slide out tray
- Microwave oven and high temp oven
- 10.4 LCD touch screen monitor
- Total of 4 single 230VAC / 50 Hz universal power outlets

Entertainment Features

- CD/DVD/MP3 Player
- Multi-disk CD Player
- One forward bulkhead monitor and one aft bulkhead monitor
- Honeywell Swift 64 Wi-Fi

EXTERIOR

Fresh paint coat and touch-ups performed in 2019 at Duncan Aviation
Fuselage, INBD Winglet, Top & Bottom of Wings are Matterhorn White
Door Trims and Registration are Gamma Grey
Underside of Fuselage, Logo, and Winglet are Gloss Dark Green
Stripe(s) and Winglet are Medium Gold

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aérodrome de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aérodrome de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aéroport de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aéroport de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aéroport de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aéroport de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aérodrome de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero

2009 Bombardier Global 5000 S/N 9315



JETCO SAS - Aéroport de Vannes-Meucon, Hangar Rouge - 56250 Monterblanc – France
Tel : +33 2 57 620 620 - RCS Vannes 840 992 523 - <http://www.jetco.aero> - contact@jetco.aero